

A low-angle shot of a white and blue Sound Transit train. The train has a teal and blue wave-like graphic on its side. The windows are dark, and the train is positioned under a glass and steel structure, likely a station platform.

# Fall Restraint Repairs

Operations & Administration Committee, November 2, 2017

 **SOUNDTRANSIT**

# Fall Restraint Repairs



Mountlake Terrace East Bus Platform

# Fall Restraint Repairs



Mountlake Terrace West Bus Platform

# Fall Restraint Repairs



2017/09/19  
Mountlake Terrace Pedestrian Bridge from CT Garage

# Fall Restraint Repairs



View of complex roof structure requiring addition of fixed mount ladders

