

A low-angle shot of a white and blue Sound Transit train. The train has a teal wave-like graphic on its side. The windows are dark, and the train is positioned under a glass and steel structure, likely a station platform. The lighting is bright, suggesting daytime.

Fall Restraint Repairs

Operations & Administration Committee, October 5, 2017

 **SOUNDTRANSIT**

Fall Restraint Repairs



Mountlake Terrace East Bus Platform

Fall Restraint Repairs



2017/09/19

Mountlake Terrace West Bus Platform

Fall Restraint Repairs



2017/09/19
Mountlake Terrace Pedestrian Bridge from CT Garage

Fall Restraint Repairs



View of complex roof structure requiring addition of fixed mount ladders

